

14 June 67		SEC. CL.	ORIGIN	CONTROL NO.	
		S	C/PB,IPD	-----	
DATE OF DOC	DATE REC'D	DATE OUT	SUSPENSE DATE	CROSS REFERENCE OR POINT OF FILING	
	15 June 67				
TO FROM SUBJ.	C/OB,IPD Info TDS C/PB,IPD Report on Plotter Malfunction			ROUTING	
				BN <i>16 June 67</i>	
				DS <i>SR</i>	
					
COURIER NO.	ANSWERED	NO REPLY		2	

25X1

25X1

Action

Declass Review by
NIMA/DOD

UNCLASSIFIED CONFIDENTIAL SECRET

CENTRAL INTELLIGENCE AGENCY
OFFICIAL ROUTING SLIP

TO	NAME AND ADDRESS	DATE	INITIALS
1	Asst. for Technical Development Rm 4N-412 		
2	25X1		
3			
4			
5			

ACTION	DIRECT REPLY	PREPARE REPLY
APPROVAL	DISPATCH	RECOMMENDATION
COMMENT	FILE	RETURN
CONCURRENCE	INFORMATION	SIGNATURE

Remarks: *Frank*
I believe we have action on this! please contact IPD for details. we do not have the sample —
DS 25X1

FOLD HERE TO RETURN TO SENDER

FROM: NAME, ADDRESS AND PHONE NO.		DATE
Chief, PRB/IPD Rm 4S474 		14 Jun 67
UNCLASSIFIED	CONFIDENTIAL	SECRET

FORM NO. 2-61 237 Use previous editions

(40)
U.S. GOVERNMENT PRINTING OFFICE : 1961 O-587282

SECRET

14 June 1967

MEMORANDUM FOR: Chief, Operations Branch, IPD

THROUGH: Chief, Information Processing Division, NPIC

SUBJECT: Report on [] Plotter Malfunction

1. The attached map overlay plot is a typical sample of recent output from the [] Plotter. This was number five(5) from a series of 12 plots delivered to PRB/IPD on the morning of 12 June 1967.

2. This sample is submitted as an example of the problems which still exist in the plotter functioning. Rounded corners indicate a malfunction in the plotter slowdown mechanism. The ink skipping problem is readily noticeable.

3. Since this was supposedly the first operational mission for the plotter, and other missions are upcoming shortly, it is requested that work on the plotter be expedited in order that usable results might be produced.

- S -

[]
Chief, Programming Branch, IPD

cc: NPIC/TD wo/att

Distribution:

- Orig. - Addressee w/att.
- 2 - NPIC/IPD/PRB wo/att.

SECRET

